

**Top (AA-F):** Service packages – fixed prices based on an hourly rate  
**Below:** Prices of common service and upgrade package combinations  
**Prices incl. VAT:** German VAT applies for EU citizens only

**CLA**= Cleaning, Lubricating, Adjusting; **FAC**= baierfoto Film Advance Control unit; **TSR**= baierfoto Two Step Release

	Hours of Work	Hourly Rate	Total before VAT	incl. VAT	Additional charges for Exakta 66	
<b>Red = before VAT</b> <b>Blue = incl. VAT @ 19 per cent</b>						
<b>AA: Checks:</b> shutter cloth, film advance system, mirror, flange focal distance, light seals, glass of focusing field lens, shutter speeds ( <b>applies only if no other work order is given</b> )	0,25	35,00 €	8,75 €	10,41 €		
A: Removing dials, levers and top cover, Examining film advance system for mechanical failures	0,5	35,00 €	17,50 €	20,83 €		
B: Disassembling camera, cleaning, lubricating, reassembling of inner unit incl. fix of little malfunctions, Testing tensile strength of shutter straps fabric	2,5	35,00 €	87,50 €	104,13 €		
C: mounting inner unit into housing, adjust film pressure plate, flange focal distance, stop down lever, frame counter	1,5	35,00 €	52,50 €	62,48 €	20,00 €	23,80 €
D: Adjusting shutter speeds	0,75	35,00 €	26,25 €	31,24 €		
E: Adjusting position of screen and focus including readjustment of stop down lever	1	35,00 €	35,00 €	41,65 €		
F: Mounting top cover, dials and levers, adjusting stop cam of advance lever, final control of shutter speeds, film advance, frame counter and flash synch.	1	35,00 €	35,00 €	41,65 €		
<b>CLA (sum of A to F)</b>			<b>250,00 €</b>	<b>300,00 €</b>	20,00 €	23,80 €
<b>FAC</b>			<b>100,00 €</b>	<b>119,00 €</b>		
<b>TSA w/o CLA (not recommended)</b>			<b>210,00 €</b>	<b>250,00 €</b>	20,00 €	23,80 €
<b>CLA+FAC</b>			<b>330,00 €</b>	<b>390,00 €</b>	20,00 €	23,80 €
<b>CLA+TSR</b>			<b>350,00 €</b>	<b>417,00 €</b>	30,00 €	35,70 €
<b>CLA+FAC+TSR</b>			<b>425,00 €</b>	<b>500,00 €</b>	25,00 €	29,75 €
<b>Replacement of curtain No. 2 straps if needed additional charge:</b>			<b>27,00 €</b>	<b>32,00 €</b>		
<b>Shutter speeds records and diagrams (PDF and/or printout)</b>			<b>4,20 €</b>	<b>5,00 €</b>		

**A not uncommon issue: Shutter straps tearing**

With age, the shutter straps often lose their tensile strength and are unable to withstand the sudden braking force they are subjected to at the end of the shutter curtain movement. Cleaning and lubricating increases the peak load of the shutter movement as the 'natural' brake effect of old grease has been eliminated. As a result, it is not uncommon for the straps of the second curtain to tear during adjusting after cleaning and lubricating. Due to lower load peaks the first curtain is not concerned normally.

I deal with this issue as follows:

When dismantling the camera I measure the tensile strength of a sample piece of the fabric. If the tensile strength is insufficient the two straps of curtain 2 are replaced.

Testing the tensile strength is included in the CLA service. Replacing the straps costs an additional 27 Euros (**32 Euros incl. VAT**).